SITE: IDEAL COOPERAGE
DATE: MAY 17-22, 1991
PHOTOS BY: P. DI PASCA (TAT)
PHOTOS BY: 2ND & 3RD WEEKS
DESCRIPTION: OF SITE ACTIVITY
(INCLUDES TEST PITS)



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 17, 1991 PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Retrieval of waxy solid drum: from base of southern slope near railroad tracks







SITE: Ideal Cooperage, Jersey City, NJ DATE: May 17, 1991 PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Retrieval of waxy solid drums from base of southern slope near railroad tracks



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 17, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Leaking waxy solid drum in southern area of site



SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 17, 1991
PHOTO BY: P. Di Pasca, Weston TAT
DESCRIPTION: Demobilization of John
Deere 490D excavator



SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 17, 1991
PHOTO BY: P. Di Pasca, Weston TAT
DESCRIPTION: Retrieval of waxy solid drum
from base of southern slope
near railroad tracks



SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 17, 1991
PHOTO BY: P. Di Pasca, Weston TAT

S DESCRIPTION: Retrieval of waxy solid drums
from base of southern slope
near railroad tracks



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 17, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Leaking waxy solid drum in southern area of site



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 17, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Demobilization of John Deere 490D excavator



SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 21, 1991
PHOTO BY: P. Di Pasca, Weston TAT
DESCRIPTION: Case 580K backhoe mobilized
to site



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 21, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Case 580K backhoe mobilized to site



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 22, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Close-up of test pit # 1



SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 22, 1991
PHOTO BY: P. Di Pasca, Weston TAT
DESCRIPTION: Start of test pit # 3
excavation

3



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 22, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Close-up of soil from test

pit # 3; depth = 1-2 feet;

HNu reading = 20-60



SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 22, 1991
PHOTO BY: P. Di Pasca, Weston TAT
DESCRIPTION: Test pit # 2 after
backfilling



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 22, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Excavation of test pit # 3



SITE: Ideal Cooperage, Jersey City, NJ

DATE: May 22, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Close-up of test pit # 3



SITE: Ideal Cooperage, Jersey City, NJ

DATE: May 22, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Excavation of test pit # 4









SITE: Ideal Cooperage, Jersey City, NJ
DATE: May 22, 1991
PHOTO BY: P. Di Pasca, Weston TAT
DESCRIPTION: Sampling of soil from test
pit # 5; depth = 5-5.5 feet







SITE: Ideal Cooperage, Jersey City, NJ DATE: May 22, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Sampling of soil from test

pit # 5; depth = 5-5.5 feet











SITE: Ideal Cooperage, Jersey City, NJ DATE: May 22, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Test pit # 2 after backfilling



SITE: Ideal Cooperage, Jersey City, NJ DATE: May 22, 1991 PHOTO BY: P. Di Pasca, Weston TAT DESCRIPTION: Close-up of soil from test

pit # 3; depth = 1-2 feet;

HNu reading = 20-60



SITE: Ideal Cooperage, Jersey City, NJ

DATE: May 22, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Excavation of test pit # 6

UN





